

UNIT NUMBER SWMU 113

UNIT NAME Rubble pile 11

REGULATORY STATUS: AOC

LOCATION: Jim Allen Road at Little Bayou N-9100 W-1700

APPROXIMATE DIMENSIONS: Concrete slabs used to stablize bank on approx. 100 ft  
of creek bank

FUNCTION: Stabilize creek bank, control erosion

OPERATIONAL STATUS: In place

DATES OPERATED: 1986 to present

SITE/PROCESS DESCRIPTION: Concrete slabs are used to cover creek bank under  
new bridge and a few feet of bank upstream and  
downstream of bridge



WASTE DESCRIPTION: Concrete rubble believed to be from PGDP roads

WASTE QUANTITY: Approx. ten cu yds of concrete


DESCRIPTION OF RELEASE: Rubble survey did not identify any contamination on  
rubble itself. Soil investigation revealed  
contamination approx. three times over background.

DOCUMENTATION OF NO RELEASE: N/A

RFI NECESSARY: YES



1200 0 1200 2400 Feet

A horizontal scale bar with alternating black and white segments, corresponding to the 1200, 0, 1200, and 2400 feet markings.